

Technical Bulletin

Date: 8th June 2022

Doc. No: PAGTB702

Product: Mini PAGlink Gold Mount Batteries:
MPL50 Model 7141 & MPL99 Model 7241.

Subject: Incompatibility between Mini PAGlink Gold Mount batteries and Anton/
Bauer chargers, with the potential for overheating or fire.

Details: PAG has identified an incompatibility between its Mini PAGlink Gold Mount batteries and Anton/Bauer chargers which can lead to the battery overheating. PAG customers should not use Anton/Bauer chargers to charge Mini PAGlink Gold Mount batteries until the batteries have received a firmware update greater than V3.5.

If customers need to borrow a PAG charger, they can contact support@paguk.com and PAG will endeavour to help them, where possible.

PAGlink Gold Mount Batteries HC-PL94 Model 9306 and HC-PL150 Model 9313 are not affected.

PAG is not aware of any other chargers that present the same problem.

Solution: PAG will provide a battery firmware update, via a tool that connects to the battery contacts. The update will enable customers to charge their Mini PAGlink Gold Mount batteries using Anton/Bauer chargers.